

**Flood Control Project Maintenance  
Levee Inspections****2015 Channel Summary Report****Overall Unit and Item Ratings****Fairfield Suisun Sewer District**

---

**Laurel Creek**

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

**Ledgewood Creek**

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

**McCoy Creek**

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

**Union Avenue Diversion**

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

**Flood Control Project Maintenance****Unit Cover Sheet****2015 Channel Inspection Results****Fairfield Suisun Sewer District**

Channel
Laurel Creek

Channel Rating	<b>A</b>
Date of Inspection	08/05/2015 - 08/06/2015
DWR Inspector	Jai Lor
Accompanied By	Kevin Cullen City of Fairfield

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Cement Hill Rd / Up**

Rating **	A	Issue No.	1	GPS Lat/Long
Issue Type +	Ma	Location *		38.279936 °
Category	Rivers, Channels & Designated Flood			-122.018353 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_15_c_2012_1			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Photo 1 of 2 : CH\_2015\_NA0035\_15\_1\_20150817\_00045.jpg



View of Laurel Creek looking upstream. Summer 2015.

Rating **	A	Issue No.	1 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		38.279936 °
Category	Rivers, Channels & Designated Flood			-122.018353 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_15_c_2012_1			

Photo 2 of 2 : CH\_2015\_NA0035\_15\_1\_20150612\_00001.jpg



A view looking upstream from Cement Hill Rd. Summer 2014

Rating **	A	Issue No.	2	GPS Lat/Long
Issue Type +	Ma	Location *		38.279936 °
Category	Rivers, Channels & Designated Flood			-122.018353 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_15_c_2012_2			

Action/Comments

Inspector Comments: No shoaling or sedimentation present.

No Photos

**\* Location**  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Cement Hill Rd / Up (cont)**

Rating **	A	Issue No.	3	GPS Lat/Long
Issue Type +	Ma	Location *		38.279937 °
Category	Rivers, Channels & Designated Flood			-122.018353 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_15_c _ 2012_3			

Action/Comments

Inspector Comments: No erosion encroaching into the channel.

No Photos

Rating **	A	Issue No.	4	GPS Lat/Long
Issue Type +	Ma	Location *		38.279936 °
Category	Rivers, Channels & Designated Flood			-122.018354 °
Item	Revetments			
DWR ID	DWR_NA0035_15_c _ 2012_4			

Action/Comments

Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.

No Photos

Rating **	A	Issue No.	5	GPS Lat/Long
Issue Type +	Ma	Location *		38.279793 °
Category	Rivers, Channels & Designated Flood			-122.018267 °
Item	Encroachments			
DWR ID	DWR_NA0035_15_c _ 2012_5			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Cement Hill Rd / Down**

Rating **	A	Issue No.	6	GPS Lat/Long
Issue Type +	Ma	Location *		38.279937 °
Category	Rivers, Channels & Designated Flood			-122.018353 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_15_c_2012_6			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 2 : CH\_2015\_NA0035\_15\_6\_20150817\_00046.jpg



Looking downstream from Cement Hill Rd. Summer 2015.

Photo 2 of 2 : CH\_2015\_NA0035\_15\_6\_20150612\_00009.jpg



A view looking downstream from Cement Hill Rd. Summer 2014

Rating **	A	Issue No.	7	GPS Lat/Long
Issue Type +	Ma	Location *		38.279937 °
Category	Rivers, Channels & Designated Flood			-122.018353 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_15_c_2012_7			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View				
Cement Hill Rd / Down (cont)				
Rating **	A	Issue No.	8	GPS Lat/Long
Issue Type +	Ma	Location *		38.279937
Category	Rivers, Channels & Designated Flood			-122.018353
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_15_c _ 2012_8			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel.				

No Photos

Rating **	A	Issue No.	9	GPS Lat/Long
Issue Type +	Ma	Location *		38.279937
Category	Rivers, Channels & Designated Flood			-122.018354
Item	Revetments			
DWR ID	DWR_NA0035_15_c _ 2012_9			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.				

Photo 1 of 1 : CH\_2015\_NA0035\_15\_9\_20150817\_00047.jpg



View of revetment on the left bank looking downstream. Summer 2015.

Rating **	A	Issue No.	10	GPS Lat/Long
Issue Type +	Ma	Location *		38.279793
Category	Rivers, Channels & Designated Flood			-122.018267
Item	Encroachments			
DWR ID	DWR_NA0035_15_c _ 2012_10			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Air Base Parkway / Up**

Rating **	A	Issue No.	11	GPS Lat/Long
Issue Type +	Ma	Location *		38.272637 °
Category	Rivers, Channels & Designated Flood			-122.016114 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_15_c_2012_11			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 2 : CH\_2015\_NA0035\_15\_11\_20150817\_00048.jpg



Looking upstream from Air Base Pkwy. Summer 2015.

Rating **	A	Issue No.	11 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		38.272637 °
Category	Rivers, Channels & Designated Flood			-122.016114 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_15_c_2012_11			

Photo 2 of 2 : CH\_2015\_NA0035\_15\_11\_20150612\_00011.jpg



Looking upstream from Air Base Pkwy. Summer 2014

Rating **	A	Issue No.	12	GPS Lat/Long
Issue Type +	Ma	Location *		38.272632 °
Category	Rivers, Channels & Designated Flood			-122.016113 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_15_c_2012_12			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

**\* Location**  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Air Base Parkway / Up (cont)**

Rating **	A	Issue No.	13	GPS Lat/Long
Issue Type +	Ma	Location *		38.272632 °
Category	Rivers, Channels & Designated Flood			-122.016113 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_15_c _ 2012_13			

Action/Comments

Inspector Comments: No erosion encroaching into the channel.

No Photos

Rating **	A	Issue No.	14	GPS Lat/Long
Issue Type +	Ma	Location *		38.272632 °
Category	Rivers, Channels & Designated Flood			-122.016112 °
Item	Revetments			
DWR ID	DWR_NA0035_15_c _ 2012_14			

Action/Comments

Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.

No Photos

Rating **	A	Issue No.	15	GPS Lat/Long
Issue Type +	Ma	Location *		38.272625 °
Category	Rivers, Channels & Designated Flood			-122.015993 °
Item	Encroachments			
DWR ID	DWR_NA0035_15_c _ 2012_15			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Air Base Parkway / Down**

Rating **	A	Issue No.	<b>16</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.272633 °
Category	Rivers, Channels & Designated Flood			-122.016110 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_15_c_2012_16			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Photo 1 of 2 : CH\_2015\_NA0035\_15\_16\_20150817\_00049.jpg



Looking downstream from Air Base Pkwy. Summer 2015.

Photo 2 of 2 : CH\_2015\_NA0035\_15\_16\_20150612\_00013.jpg



A view looking towards Nightingale from Air Base Pkwy. Summer 2014

Rating **	A	Issue No.	<b>17</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.272631 °
Category	Rivers, Channels & Designated Flood			-122.016111 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_15_c_2012_17			

Action/Comments

Inspector Comments: No shoaling or sedimentation present.

No Photos

**\* Location**  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View				
Air Base Parkway / Down (cont)				
Rating **	A	Issue No.	18	GPS Lat/Long
Issue Type +	Ma	Location *		38.272632 °
Category	Rivers, Channels & Designated Flood			-122.016109 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_15_c _ 2012_18			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel.				

No Photos

Rating **	A	Issue No.	19	GPS Lat/Long
Issue Type +	Ma	Location *		38.272631 °
Category	Rivers, Channels & Designated Flood			-122.016109 °
Item	Revetments			
DWR ID	DWR_NA0035_15_c _ 2012_19			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.				
No Photos				

Rating **	A	Issue No.	20	GPS Lat/Long
Issue Type +	Ma	Location *		38.272625 °
Category	Rivers, Channels & Designated Flood			-122.015993 °
Item	Encroachments			
DWR ID	DWR_NA0035_15_c _ 2012_20			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Meadowlark Dr / Up**

Rating **	A	Issue No.	<b>21</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.268244 °
Category	Rivers, Channels & Designated Flood			-122.017216 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_15_c_2012_21			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded. The palm trees should be removed.

Photo 1 of 2 : CH\_2015\_NA0035\_15\_21\_20150817\_00050.jpg



Looking upstream from Meadowlark Dr. Summer 2015.

Photo 2 of 2 : CH\_2015\_NA0035\_15\_21\_20150612\_00015.jpg



Looking upstream from Meadowlark Dr. Summer 2014

Rating **	A	Issue No.	<b>22</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.268244 °
Category	Rivers, Channels & Designated Flood			-122.017216 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_15_c_2012_22			

Action/Comments

Inspector Comments: No shoaling or sedimentation present.

No Photos

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Meadowlark Dr / Up (cont)**

Rating **	A	Issue No.	23	GPS Lat/Long
Issue Type +	Ma	Location *		38.268245 °
Category	Rivers, Channels & Designated Flood			-122.017216 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_15_c _ 2012_23			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel.				

No Photos

Rating **	A	Issue No.	24	GPS Lat/Long
Issue Type +	Ma	Location *		38.268245 °
Category	Rivers, Channels & Designated Flood			-122.017216 °
Item	Revetments			
DWR ID	DWR_NA0035_15_c _ 2012_24			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.				

No Photos

Rating **	A	Issue No.	25	GPS Lat/Long
Issue Type +	Ma	Location *		38.268240 °
Category	Rivers, Channels & Designated Flood			-122.017115 °
Item	Encroachments			
DWR ID	DWR_NA0035_15_c _ 2012_25			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Meadowlark Dr / Down**

Rating **	A	Issue No.	<b>26</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.268245 °
Category	Rivers, Channels & Designated Flood			-122.017216 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_15_c_2012_26			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Photo 1 of 2 : CH\_2015\_NA0035\_15\_26\_20150817\_00051.jpg



Looking downstream from Meadowlark Dr. Summer 2015.

Photo 2 of 2 : CH\_2015\_NA0035\_15\_26\_20150612\_00017.jpg



A view looking downstream from Meadowlark Dr. Summer 2014

Rating **	A	Issue No.	<b>27</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.268245 °
Category	Rivers, Channels & Designated Flood			-122.017216 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_15_c_2012_27			

Action/Comments

Inspector Comments: No shoaling or sedimentation present.

No Photos

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Meadowlark Dr / Down (cont)**

Rating **	A	Issue No.	28	GPS Lat/Long
Issue Type +	Ma	Location *		38.268245 °
Category	Rivers, Channels & Designated Flood			-122.017216 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_15_c _ 2012_28			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel.				


No Photos

Rating **	A	Issue No.	29	GPS Lat/Long
Issue Type +	Ma	Location *		38.268245 °
Category	Rivers, Channels & Designated Flood			-122.017216 °
Item	Revetments			
DWR ID	DWR_NA0035_15_c _ 2012_29			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.				

No Photos

Rating **	M	Issue No.	30	GPS Lat/Long
Issue Type +	Ma	Location *		38.268240 °
Category	Rivers, Channels & Designated Flood			-122.017115 °
Item	Encroachments			
DWR ID	DWR_NA0035_15_c _ 2012_30			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

Photo 1 of 1 : CH\_2015\_NA0035\_15\_30\_20150817\_00052.jpg



Suggest removal of debris from the channel. Summer 2015.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**East Tabor Ave / Up**

Rating **	A	Issue No.	31	GPS Lat/Long
Issue Type +	Ma	Location *		38.265401
Category	Rivers, Channels & Designated Flood			-122.018316
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_15_c _ 2012_31			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded. The palm trees should be removed.				

Photo 1 of 2 : CH\_2015\_NA0035\_15\_31\_20150817\_00053.jpg



Looking upstream from E. Tabor Ave. Woody vegetation has been removed. Summer 2015.

Photo 2 of 2 : CH\_2015\_NA0035\_15\_31\_20150612\_00021.jpg



A view looking upstream from E. Tabor Ave. Summer 2014 Woody vegetation needs to be removed.

Rating **	A	Issue No.	32	GPS Lat/Long
Issue Type +	Ma	Location *		38.265401
Category	Rivers, Channels & Designated Flood			-122.018316
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_15_c _ 2012_32			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View				
East Tabor Ave / Up (cont)				
Rating **	A	Issue No.	33	GPS Lat/Long
Issue Type +	Ma	Location *		38.265401 °
Category	Rivers, Channels & Designated Flood			-122.018316 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_15_c _ 2012_33			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel.				

No Photos

Rating **	A	Issue No.	34	GPS Lat/Long
Issue Type +	Ma	Location *		38.265401 °
Category	Rivers, Channels & Designated Flood			-122.018316 °
Item	Revetments			
DWR ID	DWR_NA0035_15_c _ 2012_34			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.				

No Photos

Rating **	A	Issue No.	35	GPS Lat/Long
Issue Type +	Ma	Location *		38.265262
Category	Rivers, Channels & Designated Flood			-122.018443
Item	Encroachments			
DWR ID	DWR_NA0035_15_c _ 2012_35			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

Photo 1 of 1 : CH\_2015\_NA0035\_15\_35\_20150817\_00054.jpg



Debris slowly building up. Suggest monitoring and cleaning buildup. Summer 2015.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**East Tabor Ave / Down**

Rating **	A	Issue No.	36	GPS Lat/Long
Issue Type +	Ma	Location *		38.265401 °
Category	Rivers, Channels & Designated Flood			-122.018316 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_15_c _ 2012_36			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 2 : CH\_2015\_NA0035\_15\_36\_20150817\_00055.jpg



Looking downstream from E. Tabor Ave. Summer 2015.

Photo 2 of 2 : CH\_2015\_NA0035\_15\_36\_20150612\_00022.jpg



Looking downstream from E. Tabor Ave. Summer 2014

Rating **	A	Issue No.	37	GPS Lat/Long
Issue Type +	Ma	Location *		38.265401 °
Category	Rivers, Channels & Designated Flood			-122.018316 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_15_c _ 2012_37			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

**\* Location**  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**East Tabor Ave / Down (cont)**

Rating **	A	Issue No.	38	GPS Lat/Long
Issue Type +	Ma	Location *		38.265401 °
Category	Rivers, Channels & Designated Flood			-122.018316 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_15_c _ 2012_38			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel.				

No Photos

Rating **	A	Issue No.	39	GPS Lat/Long
Issue Type +	Ma	Location *		38.265401 °
Category	Rivers, Channels & Designated Flood			-122.018316 °
Item	Revetments			
DWR ID	DWR_NA0035_15_c _ 2012_39			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.				

No Photos

Rating **	A	Issue No.	40	GPS Lat/Long
Issue Type +	Ma	Location *		38.265262 °
Category	Rivers, Channels & Designated Flood			-122.018443 °
Item	Encroachments			
DWR ID	DWR_NA0035_15_c _ 2012_40			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Matthew Rd / Up**

Rating **	A	Issue No.	41	GPS Lat/Long
Issue Type +	Ma	Location *		38.259229 °
Category	Rivers, Channels & Designated Flood			-122.017713 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_15_c_2012_41			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 2 : CH\_2015\_NA0035\_15\_41\_20150817\_00056.jpg



Looking upstream rom Matthew Rd. Summer 2015.

Rating **	A	Issue No.	<b>41 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.259229 °
Category	Rivers, Channels & Designated Flood			-122.017713 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_15_c_2012_41			

Photo 2 of 2 : CH\_2015\_NA0035\_15\_41\_20150612\_00024.jpg



Looking upstream from Matthew Rd. Summer 2014

Rating **	A	Issue No.	42	GPS Lat/Long
Issue Type +	Ma	Location *		38.259272 °
Category	Rivers, Channels & Designated Flood			-122.017533 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_15_c_2012_42			
Action/Comments				
Inspector Comments: Some shoaling or sedimentation present. The flow is not impeded.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Matthew Rd / Up (cont)**

Rating **	A	Issue No.	<b>43</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.259230 °
Category	Rivers, Channels & Designated Flood			-122.017714 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_15_c _ 2012_43			

Action/Comments

Inspector Comments: No erosion encroaching into the channel.

No Photos

Rating **	A	Issue No.	<b>44</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.259230 °
Category	Rivers, Channels & Designated Flood			-122.017714 °
Item	Revetments			
DWR ID	DWR_NA0035_15_c _ 2012_44			

Action/Comments

Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.

No Photos

Rating **	A	Issue No.	<b>45</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.259272 °
Category	Rivers, Channels & Designated Flood			-122.017533 °
Item	Encroachments			
DWR ID	DWR_NA0035_15_c _ 2012_45			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Matthew Rd / Down**

Rating **	A	Issue No.	46	GPS Lat/Long
Issue Type +	Ma	Location *		38.259230 °
Category	Rivers, Channels & Designated Flood			-122.017714 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_15_c _ 2012_46			
Action/Comments				
Inspector Comments: This area is the same as upstream Railroad Avenue. I recommend the removal of the baby palm trees.				

Photo 1 of 2 : CH\_2015\_NA0035\_15\_46\_20150817\_00057.jpg



Looking downstream from Matthews Rd. Pipe goes under the railroad. Summer 2015.

Rating **	A	Issue No.	<b>46 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.259230 °
Category	Rivers, Channels & Designated Flood			-122.017714 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_15_c _ 2012_46			

Photo 2 of 2 : CH\_2015\_NA0035\_15\_46\_20150612\_00029.jpg



Looking downstream towards the five pipes that go under the railroad from Matthews Rd. Summer 2014

Rating **	A	Issue No.	47	GPS Lat/Long
Issue Type +	Ma	Location *		38.259230 °
Category	Rivers, Channels & Designated Flood			-122.017713 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_15_c _ 2012_47			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Matthew Rd / Down (cont)**

Rating **	A	Issue No.	48	GPS Lat/Long
Issue Type +	Ma	Location *		38.259230 °
Category	Rivers, Channels & Designated Flood			-122.017713 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_15_c _ 2012_48			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel.				

No Photos

Rating **	A	Issue No.	49	GPS Lat/Long
Issue Type +	Ma	Location *		38.259230 °
Category	Rivers, Channels & Designated Flood			-122.017714 °
Item	Revetments			
DWR ID	DWR_NA0035_15_c _ 2012_49			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.				

No Photos

Rating **	A	Issue No.	50	GPS Lat/Long
Issue Type +	Ma	Location *		38.259272 °
Category	Rivers, Channels & Designated Flood			-122.017533 °
Item	Encroachments			
DWR ID	DWR_NA0035_15_c _ 2012_50			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Railroad Ave / Down**

Rating **	A	Issue No.	<b>56</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.257784 °
Category	Rivers, Channels & Designated Flood			-122.017733 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_15_c_2012_56			

Action/Comments

Inspector Comments: Minimal scattered obstruction or vegetation. The flow is not impeded.

Photo 1 of 2 : CH\_2015\_NA0035\_15\_56\_20150817\_00059.jpg



Looking downstream from Railroad Ave. Summer 2015.

Photo 2 of 2 : CH\_2015\_NA0035\_15\_56\_20150612\_00031.jpg



Looking downstream from Railroad Ave. Woody vegetation has been removed. Summer 2014

Rating **	A	Issue No.	<b>57</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.257784 °
Category	Rivers, Channels & Designated Flood			-122.017734 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_15_c_2012_57			

Action/Comments

Inspector Comments: No shoaling or sedimentation present.

No Photos

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Railroad Ave / Down (cont)**

Rating **	A	Issue No.	<b>58</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.257784 °
Category	Rivers, Channels & Designated Flood			-122.017734 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_15_c _ 2012_58			

Action/Comments

Inspector Comments: No erosion encroaching into the channel.

No Photos

Rating **	A	Issue No.	<b>59</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.257785 °
Category	Rivers, Channels & Designated Flood			-122.017735 °
Item	Revetments			
DWR ID	DWR_NA0035_15_c _ 2012_59			

Action/Comments

Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.

No Photos

Rating **	A	Issue No.	<b>60</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.257752 °
Category	Rivers, Channels & Designated Flood			-122.017769 °
Item	Encroachments			
DWR ID	DWR_NA0035_15_c _ 2012_60			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Sunset Ave / Up**

Rating **	A	Issue No.	61	GPS Lat/Long
Issue Type +	Ma	Location *		38.253525 °
Category	Rivers, Channels & Designated Flood			-122.019984 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_15_c_2012_61			
Action/Comments				
Inspector Comments: Minimal scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 2 : CH\_2015\_NA0035\_15\_61\_20150817\_00060.jpg



Looking upstream from Sunset Ave. Summer 2015.

Rating **	A	Issue No.	<b>61 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.253525 °
Category	Rivers, Channels & Designated Flood			-122.019984 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_15_c_2012_61			

Photo 2 of 2 : CH\_2015\_NA0035\_15\_61\_20150612\_00033.jpg



Looking upstream the woody vegetation has been removed from Sunset Ave. Summer 2014

Rating **	A	Issue No.	62	GPS Lat/Long
Issue Type +	Ma	Location *		38.253525 °
Category	Rivers, Channels & Designated Flood			-122.019984 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_15_c_2012_62			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Sunset Ave / Up (cont)**

Rating **	A	Issue No.	<b>63</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.253525 °
Category	Rivers, Channels & Designated Flood			-122.019984 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_15_c _ 2012_63			

Action/Comments

Inspector Comments: No erosion encroaching into the channel.

No Photos

Rating **	A	Issue No.	<b>64</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.253525 °
Category	Rivers, Channels & Designated Flood			-122.019984 °
Item	Revetments			
DWR ID	DWR_NA0035_15_c _ 2012_64			

Action/Comments

Inspector Comments: Riprap displacement or scouring activity. Unwanted vegetation must be cleared and sprayed with an appropriate herbicide.

Photo 1 of 2 : CH\_2015\_NA0035\_15\_64\_20150817\_00062.jpg



View of the revetment on the left bank looking upstream. Summer 2015.

Rating **	A	Issue No.	<b>64 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.253525 °
Category	Rivers, Channels & Designated Flood			-122.019984 °
Item	Revetments			
DWR ID	DWR_NA0035_15_c _ 2012_64			

Photo 2 of 2 : CH\_2015\_NA0035\_15\_64\_20150817\_00061.jpg



View of the revetment on the right bank looking upstream. Summer

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View				
Sunset Ave / Up (cont)				
Rating **	A	Issue No.	65	GPS Lat/Long
Issue Type +	Ma	Location *		38.253525
Category	Rivers, Channels & Designated Flood			-122.019984
Item	Encroachments			
DWR ID	DWR_NA0035_15_c _ 2012_65			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View				
Sunset Ave / Down				
Rating **	M	Issue No.	66	GPS Lat/Long
Issue Type +	Ma	Location *		38.253525
Category	Rivers, Channels & Designated Flood			-122.019984
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_15_c _ 2012_66			
Action/Comments				
Inspector Comments: Vegetation growth (such as cat tails, bull rushes, bushes or saplings) or other obstructions block approximately 50% of the FCW.				

Photo 1 of 3 : CH\_2015\_NA0035\_15\_66\_20150817\_00064.jpg



Looking downstream from Sunset Ave. Suggest removal of woody vegetation. Summer 2015.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Sunset Ave / Down (cont)**

Rating **	M	Issue No.	<b>66 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.253525 °
Category	Rivers, Channels & Designated Flood			-122.019984 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_15_c _ 2012_66			

Action/Comments

Inspector Comments: Vegetation growth (such as cat tails, bull rushes, bushes or saplings) or other obstructions block approximately 50% of the FCW.

Photo 2 of 3 : CH\_2015\_NA0035\_15\_66\_20150817\_00063.jpg



Looking downstream from Sunset Ave. Some woody vegetation has been removed. Summer 2015.

Photo 3 of 3 : CH\_2015\_NA0035\_15\_66\_20150612\_00035.jpg



Looking downstream from Sunset Ave. Woody vegetation needs to be removed blocks flow. Summer 2014

Rating **	A	Issue No.	<b>67</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.253525 °
Category	Rivers, Channels & Designated Flood			-122.019984 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_15_c _ 2012_67			

Action/Comments

Inspector Comments: No shoaling or sedimentation present.

No Photos

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Sunset Ave / Down (cont)**

Rating **	A	Issue No.	<b>68</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.253525 °
Category	Rivers, Channels & Designated Flood			-122.019984 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_15_c_2012_68			

Action/Comments

Inspector Comments: No erosion encroaching into the channel.

No Photos

Rating **	A	Issue No.	<b>69</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.253525 °
Category	Rivers, Channels & Designated Flood			-122.019984 °
Item	Revetments			
DWR ID	DWR_NA0035_15_c_2012_69			

Action/Comments

Inspector Comments: No riprap displacement or scouring activity.

Photo 1 of 2 : CH\_2015\_NA0035\_15\_69\_20150817\_00066.jpg



View of the revetment on the left bank looking downstream from Sunset Ave. Summer 2015.

Rating **	A	Issue No.	<b>69 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.253525 °
Category	Rivers, Channels & Designated Flood			-122.019984 °
Item	Revetments			
DWR ID	DWR_NA0035_15_c_2012_69			

Photo 2 of 2 : CH\_2015\_NA0035\_15\_69\_20150817\_00065.jpg



View of the revetment on the right bank looking downstream from Sunset Ave. Summer 2015.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View				
Sunset Ave / Down (cont)				
Rating **	A	Issue No.	70	GPS Lat/Long
Issue Type +	Ma	Location *		38.253525 °
Category	Rivers, Channels & Designated Flood			-122.019984 °
Item	Encroachments			
DWR ID	DWR_NA0035_15_c _ 2012_70			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View				
Blossom Rd / Up				
Rating **	M	Issue No.	71	GPS Lat/Long
Issue Type +	Ma	Location *		38.253382 °
Category	Rivers, Channels & Designated Flood			-122.014862 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_15_c _ 2012_71			
Action/Comments				
Inspector Comments: Vegetation growth, cat tails, bushes, or saplings block 25% of the channel.				

Photo 1 of 3 : CH\_2015\_NA0035\_15\_71\_20150817\_00067.jpg



Looking upstream from Blossom Rd. Summer 2015.

* Location	** Rating	+ Issue Type
LS : Land Side	A : Acceptable	Ma : Maintenance Deficiency
WS : Water Side	M : Minimally Acceptable	Ob : Design & System Obsolescence
CR : Crown	U : Unacceptable	En : Enforcement
	N : Not Inspected/Rated	
	C : Corrected	
	A/W : Acceptable but Monitor & Maintain	



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Blossom Rd / Up (cont)**

Rating **	M	Issue No.	<b>71 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.253382 °
Category	Rivers, Channels & Designated Flood			-122.014862 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_15_c _ 2012_71			

Action/Comments

Inspector Comments: Vegetation growth, cat tails, bushes, or saplings block 25% of the channel.

Photo 2 of 3 : CH\_2015\_NA0035\_15\_71\_20150817\_00068.jpg



Suggest removal of woody vegetation of upstream channel. Summer 2015.

Photo 3 of 3 : CH\_2015\_NA0035\_15\_71\_20150612\_00037.jpg



Looking upstream from Blossom Rd. Summer 2014

Rating **	A	Issue No.	<b>72</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.253382 °
Category	Rivers, Channels & Designated Flood			-122.014862 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_15_c _ 2012_72			

Action/Comments

Inspector Comments: No shoaling or sedimentation present.

No Photos

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Blossom Rd / Up (cont)**

Rating **	A	Issue No.	<b>73</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.253324 °
Category	Rivers, Channels & Designated Flood			-122.014816 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_15_c _ 2012_73			

Action/Comments

Inspector Comments: No erosion encroaching into the channel.

No Photos

Rating **	A	Issue No.	<b>74</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.253324 °
Category	Rivers, Channels & Designated Flood			-122.014817 °
Item	Revetments			
DWR ID	DWR_NA0035_15_c _ 2012_74			

Action/Comments

No Photos

Rating **	A	Issue No.	<b>75</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.253382 °
Category	Rivers, Channels & Designated Flood			-122.014862 °
Item	Encroachments			
DWR ID	DWR_NA0035_15_c _ 2012_75			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Blossom Rd / Down**

Rating **	M	Issue No.	76	GPS Lat/Long
Issue Type +	Ma	Location *		38.253325 °
Category	Rivers, Channels & Designated Flood			-122.014818 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_15_c _ 2012_76			
Action/Comments				
Inspector Comments: Log jams, snags, vegetation growth (such as cat tails, bull rushes, bushes or saplings) or other obstructions block approximately 25% of the capacity.				

Photo 1 of 2 : CH\_2015\_NA0035\_15\_76\_20150817\_00069.jpg



Looking downstream from Blossom Rd. Suggest removal of woody vegetation. Summer 2015.

Photo 2 of 2 : CH\_2015\_NA0035\_15\_76\_20150612\_00039.jpg



Looking downstream from Blossom Rd. Summer 2014

Rating **	A	Issue No.	77	GPS Lat/Long
Issue Type +	Ma	Location *		38.253382 °
Category	Rivers, Channels & Designated Flood			-122.014862 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_15_c _ 2012_77			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Blossom Rd / Down (cont)**

Rating **	A	Issue No.	<b>78</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.253324 °
Category	Rivers, Channels & Designated Flood			-122.014818 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_15_c _ 2012_78			

Action/Comments

Inspector Comments: No erosion encroaching into the channel.

No Photos

Rating **	A	Issue No.	<b>79</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.253324 °
Category	Rivers, Channels & Designated Flood			-122.014818 °
Item	Revetments			
DWR ID	DWR_NA0035_15_c _ 2012_79			

Action/Comments

Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.

No Photos

Rating **	A	Issue No.	<b>80</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.253382 °
Category	Rivers, Channels & Designated Flood			-122.014862 °
Item	Encroachments			
DWR ID	DWR_NA0035_15_c _ 2012_80			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Worley Rd / Up**

Rating **	A	Issue No.	81	GPS Lat/Long
Issue Type +	Ma	Location *		38.253311 °
Category	Rivers, Channels & Designated Flood			-122.009841 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_15_c _ 2012_81			
Action/Comments				
Inspector Comments: Minimal scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 2 : CH\_2015\_NA0035\_15\_81\_20150817\_00070.jpg



Looking upstream from Worley Rd. Summer 2015.

Photo 2 of 2 : CH\_2015\_NA0035\_15\_81\_20150612\_00041.jpg



A view looking upstream from Worley Rd. Summer 2014

Rating **	A	Issue No.	82	GPS Lat/Long
Issue Type +	Ma	Location *		38.253248 °
Category	Rivers, Channels & Designated Flood			-122.009732 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_15_c _ 2012_82			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

**\* Location**  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View				
Worley Rd / Up (cont)				
Rating **	A	Issue No.	83	GPS Lat/Long
Issue Type +	Ma	Location *		38.253311 °
Category	Rivers, Channels & Designated Flood			-122.009841 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_15_c _ 2012_83			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel.				

No Photos

Rating **	A	Issue No.	84	GPS Lat/Long
Issue Type +	Ma	Location *		38.253311 °
Category	Rivers, Channels & Designated Flood			-122.009841 °
Item	Revetments			
DWR ID	DWR_NA0035_15_c _ 2012_84			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged.				
No Photos				

Rating **	A	Issue No.	85	GPS Lat/Long
Issue Type +	Ma	Location *		38.253248 °
Category	Rivers, Channels & Designated Flood			-122.009732 °
Item	Encroachments			
DWR ID	DWR_NA0035_15_c _ 2012_85			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				
No Photos				

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Worley Rd / Down**

Rating **	M	Issue No.	86	GPS Lat/Long
Issue Type +	Ma	Location *		38.253311
Category	Rivers, Channels & Designated Flood			-122.009841
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_15_c _ 2012_86			
Action/Comments				
Inspector Comments: Vegetation growth (such as cat tails, bull rushes, bushes or saplings) or other obstructions block approximately 50% of the FCW.				

Photo 1 of 2 : CH\_2015\_NA0035\_15\_86\_20150817\_00071.jpg



Looking downstream from Worley Road. Suggest removal of woody vegetation. Summer 2015.

Rating **	M	Issue No.	<b>86 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.253311 °
Category	Rivers, Channels & Designated Flood			-122.009841 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_15_c _ 2012_86			

Photo 2 of 2 : CH\_2015\_NA0035\_15\_86\_20150612\_00043.jpg



A view looking downstream from Worley Rd. Summer 2014

Rating **	A	Issue No.	87	GPS Lat/Long
Issue Type +	Ma	Location *		38.253248
Category	Rivers, Channels & Designated Flood			-122.009732
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_15_c _ 2012_87			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View				
Worley Rd / Down (cont)				
Rating **	A	Issue No.	88	GPS Lat/Long
Issue Type +	Ma	Location *		38.253311 °
Category	Rivers, Channels & Designated Flood			-122.009841 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_15_c _ 2012_88			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel.				

No Photos

No Photos

Rating **	A	Issue No.	89	GPS Lat/Long
Issue Type +	Ma	Location *		38.253311 °
Category	Rivers, Channels & Designated Flood			-122.009841 °
Item	Revetments			
DWR ID	DWR_NA0035_15_c _ 2012_89			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged.				

No Photos

No Photos

Rating **	M	Issue No.	90	GPS Lat/Long
Issue Type +	Ma	Location *		38.253248 °
Category	Rivers, Channels & Designated Flood			-122.009732 °
Item	Encroachments			
DWR ID	DWR_NA0035_15_c _ 2012_90			
Action/Comments				
Inspector Comments: Trash and few obstructions were present within the project easement area.				

Photo 1 of 2 : CH\_2015\_NA0035\_15\_90\_20150817\_00073.jpg




Photo 1 of 2 : CH\_2015\_NA0035\_15\_90\_20150817\_00073.jpg



Perspective view of the debris looking downstream from Worley Rd.  
Summer 2015.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View				
Worley Rd / Down (cont)				
Rating **	M	Issue No.	90 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		38.253248 °
Category	Rivers, Channels & Designated Flood			-122.009732 °
Item	Encroachments			
DWR ID	DWR_NA0035_15_c _ 2012_90			
Action/Comments				
Inspector Comments: Trash and few obstructions were present within the project easement area.				

Photo 2 of 2 : CH\_2015\_NA0035\_15\_90\_20150817\_00072.jpg



Suggest removal of debris on the downstream side of the channel.  
Summer 2015.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance****Unit Cover Sheet****2015 Channel Inspection Results****Fairfield Suisun Sewer District**

Channel
Ledgewood Creek

Channel Rating	<b>A</b>
Date of Inspection	08/05/2015 - 08/06/2015
DWR Inspector	Jai Lor
Accompanied By	Kevin Cullen City of Fairfield

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Astoria Drive / Up**

Rating **	A	Issue No.	1	GPS Lat/Long
Issue Type +	Ma	Location *		38.256296 °
Category	Rivers, Channels & Designated Flood			-122.073705 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_17_c _ 2012_1			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation.				

Photo 1 of 2 : CH\_2015\_NA0035\_17\_1\_20150817\_00053.jpg



Looking upstream from Astoria Dr. Trees have been trimmed. Summer 2015.

Rating **	A	Issue No.	1 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		38.256296 °
Category	Rivers, Channels & Designated Flood			-122.073705 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_17_c _ 2012_1			

Photo 2 of 2 : CH\_2015\_NA0035\_17\_1\_20150612\_00002.jpg



Looking upstream from Astoria Dr. Trees need to be trimmed up or removed from channel. Summer 2014

Rating **	A	Issue No.	2	GPS Lat/Long
Issue Type +	Ma	Location *		38.256296 °
Category	Rivers, Channels & Designated Flood			-122.073705 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_17_c _ 2012_2			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View				
Astoria Drive / Up (cont)				
Rating **	A	Issue No.	3	GPS Lat/Long
Issue Type +	Ma	Location *		38.256296 °
Category	Rivers, Channels & Designated Flood			-122.073705 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_17_c _ 2012_3			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel.				

No Photos

No Photos

Rating **	A	Issue No.	4	GPS Lat/Long
Issue Type +	Ma	Location *		38.256296 °
Category	Rivers, Channels & Designated Flood			-122.073705 °
Item	Revetments			
DWR ID	DWR_NA0035_17_c _ 2012_4			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.				

No Photos

No Photos

Rating **	A	Issue No.	5	GPS Lat/Long
Issue Type +	Ma	Location *		38.256296 °
Category	Rivers, Channels & Designated Flood			-122.073705 °
Item	Encroachments			
DWR ID	DWR_NA0035_17_c _ 2012_5			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Astoria Drive / Down**

Rating **	A	Issue No.	6	GPS Lat/Long
Issue Type +	Ma	Location *		38.256296 °
Category	Rivers, Channels & Designated Flood			-122.073705 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_17_c _ 2012_6			

Action/Comments

Inspector Comments: Vegetation has been maintained and does not appear to impede flow.

Rating **	A	Issue No.	6 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		38.256296 °
Category	Rivers, Channels & Designated Flood			-122.073705 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_17_c _ 2012_6			

Rating **	A	Issue No.	6 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		38.256296 °
Category	Rivers, Channels & Designated Flood			-122.073705 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_17_c _ 2012_6			

Photo 1 of 3 : CH\_2015\_NA0035\_17\_6\_20150817\_00054.jpg



Looking downstream from Astoria Dr. Summer 2015.

Photo 2 of 3 : CH\_2015\_NA0035\_17\_6\_20150612\_00009.jpg



Looking downstream from Astoria Dr. Blackberries need to be removed as they will impeded the flow. Summer 2014

Photo 3 of 3 : CH\_2015\_NA0035\_17\_6\_20150612\_00008.jpg



Corrected view of blackberries from Astoria Drive. Aug. 27, 2014

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View				
Astoria Drive / Down (cont)				
Rating **	A	Issue No.	7	GPS Lat/Long
Issue Type +	Ma	Location *		38.256296 °
Category	Rivers, Channels & Designated Flood			-122.073705 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_17_c _ 2012_7			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	8	GPS Lat/Long
Issue Type +	Ma	Location *		38.256296 °
Category	Rivers, Channels & Designated Flood			-122.073705 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_17_c _ 2012_8			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel.				

No Photos

Rating **	A	Issue No.	9	GPS Lat/Long
Issue Type +	Ma	Location *		38.256296 °
Category	Rivers, Channels & Designated Flood			-122.073705 °
Item	Revetments			
DWR ID	DWR_NA0035_17_c _ 2012_9			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.				
No Photos				

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View				
Astoria Drive / Down (cont)				
Rating **	A	Issue No.	10	GPS Lat/Long
Issue Type +	Ma	Location *		38.256296
Category	Rivers, Channels & Designated Flood			-122.073705
Item	Encroachments			
DWR ID	DWR_NA0035_17_c _ 2012_10			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View				
Springfield Dr. / Up				
Rating **	A	Issue No.	11	GPS Lat/Long
Issue Type +	Ma	Location *		38.254594
Category	Rivers, Channels & Designated Flood			-122.073608
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_17_c _ 2012_11			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 2 : CH\_2015\_NA0035\_17\_11\_20150817\_00055.jpg



Looking upstream from Springfield Dr. Summer 2015.

Photo 2 of 2 : CH\_2015\_NA0035\_17\_11\_20150612\_00010.jpg



A view looking upstream from Springfield Dr. Summer 2014

* Location	** Rating	+ Issue Type
LS : Land Side	A : Acceptable	Ma : Maintenance Deficiency
WS : Water Side	M : Minimally Acceptable	Ob : Design & System Obsolescence
CR : Crown	U : Unacceptable	En : Enforcement
	N : Not Inspected/Rated	
	C : Corrected	
	A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Springfield Dr. / Up (cont)**

Rating **	A	Issue No.	12	GPS Lat/Long
Issue Type +	Ma	Location *		38.254595 °
Category	Rivers, Channels & Designated Flood			-122.073611 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_17_c _ 2012_12			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	13	GPS Lat/Long
Issue Type +	Ma	Location *		38.254595 °
Category	Rivers, Channels & Designated Flood			-122.073610 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_17_c _ 2012_13			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel.				

No Photos

Rating **	A	Issue No.	14	GPS Lat/Long
Issue Type +	Ma	Location *		38.254594 °
Category	Rivers, Channels & Designated Flood			-122.073609 °
Item	Revetments			
DWR ID	DWR_NA0035_17_c _ 2012_14			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View				
Springfield Dr. / Up (cont)				
Rating **	A	Issue No.	15	GPS Lat/Long
Issue Type +	Ma	Location *		38.254582
Category	Rivers, Channels & Designated Flood			-122.073597
Item	Encroachments			
DWR ID	DWR_NA0035_17_c _ 2012_15			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View				
Springfield Dr. / Down				
Rating **	A	Issue No.	16	GPS Lat/Long
Issue Type +	Ma	Location *		38.254594
Category	Rivers, Channels & Designated Flood			-122.073608
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_17_c _ 2012_16			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 2 : CH\_2015\_NA0035\_17\_16\_20150817\_00056.jpg



Looking downstream from Springfield Dr. Summer 2015.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View				
Springfield Dr. / Down (cont)				
Rating **	A	Issue No.	16 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		38.254594 °
Category	Rivers, Channels & Designated Flood			-122.073608 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_17_c _ 2012_16			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 2 of 2 : CH\_2015\_NA0035\_17\_16\_20150612\_00012.jpg



A view looking downstream from Springfield Dr. towards the junction of main channel. Summer 2014

Rating **	A	Issue No.	17	GPS Lat/Long
Issue Type +	Ma	Location *		38.254594
Category	Rivers, Channels & Designated Flood			-122.073610
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_17_c _ 2012_17			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	18	GPS Lat/Long
Issue Type +	Ma	Location *		38.254594
Category	Rivers, Channels & Designated Flood			-122.073610
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_17_c _ 2012_18			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Springfield Dr. / Down (cont)**

Rating **	A	Issue No.	19	GPS Lat/Long
Issue Type +	Ma	Location *		38.254594 °
Category	Rivers, Channels & Designated Flood			-122.073609 °
Item	Revetments			
DWR ID	DWR_NA0035_17_c _ 2012_19			

Action/Comments

Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.

No Photos

Rating **	A	Issue No.	20	GPS Lat/Long
Issue Type +	Ma	Location *		38.254582 °
Category	Rivers, Channels & Designated Flood			-122.073597 °
Item	Encroachments			
DWR ID	DWR_NA0035_17_c _ 2012_20			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

Check Point / View

**Rockville Road / Up**

Rating **	A	Issue No.	21	GPS Lat/Long
Issue Type +	Ma	Location *		38.249841 °
Category	Rivers, Channels & Designated Flood			-122.072646 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_17_c _ 2012_21			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Photo 1 of 2 : CH\_2015\_NA0035\_17\_21\_20150817\_00057.jpg



Looking upstream from Rockville Rd. Summer 2015.

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Rockville Road / Up (cont)**

Rating **	A	Issue No.	<b>21 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.249841 °
Category	Rivers, Channels & Designated Flood			-122.072646 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_17_c _ 2012_21			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Photo 2 of 2 : CH\_2015\_NA0035\_17\_21\_20150612\_00014.jpg



Looking upstream from Rockville Rd. Summer 2014

Rating **	A	Issue No.	<b>22</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.249841 °
Category	Rivers, Channels & Designated Flood			-122.072646 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_17_c _ 2012_22			

Action/Comments

Inspector Comments: No shoaling or sedimentation present.

No Photos

Rating **	A	Issue No.	<b>23</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.249841 °
Category	Rivers, Channels & Designated Flood			-122.072646 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_17_c _ 2012_23			

Action/Comments

Inspector Comments: No erosion encroaching into the channel.

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Rockville Road / Up (cont)**

Rating **	A	Issue No.	<b>25</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.249960 °
Category	Rivers, Channels & Designated Flood			-122.072670 °
Item	Encroachments			
DWR ID	DWR_NA0035_17_c _ 2012_25			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

Rating **	A	Issue No.	<b>24</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.249840 °
Category	Rivers, Channels & Designated Flood			-122.072644 °
Item	Gates			
DWR ID	DWR_NA0035_17_c _ 2012_24			

Action/Comments

Inspector Comments: Flap gate has been replaced.

Photo 1 of 2 : CH\_2015\_NA0035\_17\_24\_20150612\_00016.jpg



Flap gate has been replace and tagged (Summer 2013)

Rating **	A	Issue No.	<b>24 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.249840 °
Category	Rivers, Channels & Designated Flood			-122.072644 °
Item	Gates			
DWR ID	DWR_NA0035_17_c _ 2012_24			

Photo 2 of 2 : CH\_2015\_NA0035\_17\_24\_20150612\_00017.jpg



The flap gate has not been replaced. Should have a new one installed. (2012)

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Rockville Road / Down**

Rating **	A	Issue No.	26	GPS Lat/Long
Issue Type +	Ma	Location *		38.249840 °
Category	Rivers, Channels & Designated Flood			-122.072644 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_17_c_2012_26			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 2 : CH\_2015\_NA0035\_17\_26\_20150817\_00058.jpg



Looking downstream from Rockville Rd. Summer 2015.

Rating **	A	Issue No.	<b>26 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.249840 °
Category	Rivers, Channels & Designated Flood			-122.072644 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_17_c_2012_26			

Photo 2 of 2 : CH\_2015\_NA0035\_17\_26\_20150612\_00018.jpg



Looking downstream from Rockville Rd. Summer 2014

Rating **	A	Issue No.	27	GPS Lat/Long
Issue Type +	Ma	Location *		38.249840 °
Category	Rivers, Channels & Designated Flood			-122.072645 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_17_c_2012_27			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Rockville Road / Down (cont)**

Rating **	A	Issue No.	28	GPS Lat/Long
Issue Type +	Ma	Location *		38.249841 °
Category	Rivers, Channels & Designated Flood			-122.072645 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_17_c _ 2012_28			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel.				

No Photos

Rating **	N	Issue No.	29	GPS Lat/Long
Issue Type +	Ma	Location *		38.249841 °
Category	Rivers, Channels & Designated Flood			-122.072645 °
Item	Revetments			
DWR ID	DWR_NA0035_17_c _ 2012_29			
Action/Comments				
Inspector Comments: This item does not apply to this inspection.				

No Photos

Rating **	A	Issue No.	30	GPS Lat/Long
Issue Type +	Ma	Location *		38.249960 °
Category	Rivers, Channels & Designated Flood			-122.072670 °
Item	Encroachments			
DWR ID	DWR_NA0035_17_c _ 2012_30			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Auto Mall Parkway / Up**

Rating **	A	Issue No.	<b>31</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.247663 °
Category	Rivers, Channels & Designated Flood			-122.071997 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_17_c _ 2012_31			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Photo 1 of 2 : CH\_2015\_NA0035\_17\_31\_20150817\_00059.jpg



Looking upstream from Auto Mall Pkwy under I-80. Summer 2015.

Photo 2 of 2 : CH\_2015\_NA0035\_17\_31\_20150612\_00020.jpg



Upstream view from Auto Mall Pkwy. Under I-80 and homeless camp. Summer 2014

Rating **	A	Issue No.	<b>32</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.247663 °
Category	Rivers, Channels & Designated Flood			-122.072105 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_17_c _ 2012_32			

Action/Comments

Inspector Comments: No shoaling or sedimentation present.

No Photos

**\* Location**  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View				
Auto Mall Parkway / Up (cont)				
Rating **	A	Issue No.	33	GPS Lat/Long
Issue Type +	Ma	Location *		38.247663 °
Category	Rivers, Channels & Designated Flood			-122.072105 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_17_c _ 2012_33			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel.				

No Photos

Rating **	N	Issue No.	34	GPS Lat/Long
Issue Type +	Ma	Location *		38.247663 °
Category	Rivers, Channels & Designated Flood			-122.072105 °
Item	Revetments			
DWR ID	DWR_NA0035_17_c _ 2012_34			
Action/Comments				
Inspector Comments: This item does not apply to this inspection.				

No Photos

Rating **	A	Issue No.	35	GPS Lat/Long
Issue Type +	Ma	Location *		38.247722 °
Category	Rivers, Channels & Designated Flood			-122.072105 °
Item	Encroachments			
DWR ID	DWR_NA0035_17_c _ 2012_35			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				
No Photos				

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Auto Mall Parkway / Down**

Rating **	A	Issue No.	<b>36</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.247663 °
Category	Rivers, Channels & Designated Flood			-122.072325 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_17_c_2012_36			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Photo 1 of 2 : CH\_2015\_NA0035\_17\_36\_20150817\_00062.jpg



Looking downstream from Auto Mall Pkwy. Summer 2015.

Rating **	A	Issue No.	<b>36 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.247663 °
Category	Rivers, Channels & Designated Flood			-122.072325 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_17_c_2012_36			

Photo 2 of 2 : CH\_2015\_NA0035\_17\_36\_20150612\_00023.jpg



Looking downstream from Auto Mall Pkwy. Summer 2014

Rating **	A	Issue No.	<b>37</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.247663 °
Category	Rivers, Channels & Designated Flood			-122.072105 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_17_c_2012_37			

Action/Comments

Inspector Comments: No shoaling or sedimentation present.

No Photos

**\* Location**  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View				
Auto Mall Parkway / Down (cont)				
Rating **	A	Issue No.	38	GPS Lat/Long
Issue Type +	Ma	Location *		38.247663 °
Category	Rivers, Channels & Designated Flood			-122.072105 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_17_c _ 2012_38			
Action/Comments				
Inspector Comments: No erosion encroachment into the channel.				

No Photos

Rating **	N	Issue No.	39	GPS Lat/Long
Issue Type +	Ma	Location *		38.247663 °
Category	Rivers, Channels & Designated Flood			-122.072105 °
Item	Revetments			
DWR ID	DWR_NA0035_17_c _ 2012_39			
Action/Comments				
Inspector Comments: This item does not apply to this inspection.				

No Photos

Rating **	A	Issue No.	40	GPS Lat/Long
Issue Type +	Ma	Location *		38.247722 °
Category	Rivers, Channels & Designated Flood			-122.072105 °
Item	Encroachments			
DWR ID	DWR_NA0035_17_c _ 2012_40			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Auto Mall Parkway / Down (cont)**

Rating **	A	Issue No.	82	GPS Lat/Long
Issue Type +	Ma	Location *		38.247722 °
Category	Rivers, Channels & Designated Flood			-122.072105 °
Item	Gates			
DWR ID	DWR_NA0035_17_c_2015_82			
Action/Comments				

Photo 1 of 1 : CH\_2015\_NA0035\_17\_82\_20150817\_00061.jpg



View of the gate looking downstream from Auto Mall Pkwy. Summer 2015.

Check Point / View

**Woolner Avenue / Up**

Rating **	A	Issue No.	41	GPS Lat/Long
Issue Type +	Ma	Location *		38.245298 °
Category	Rivers, Channels & Designated Flood			-122.068536 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_17_c_2012_41			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 3 : CH\_2015\_NA0035\_17\_41\_20150817\_00063.jpg



Looking upstream from Woolner Ave. Suggest removing cart from the channel. Summer 2015.

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Woolner Avenue / Up (cont)**

Rating **	A	Issue No.	<b>41 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.245298 °
Category	Rivers, Channels & Designated Flood			-122.068536 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_17_c_2012_41			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Photo 2 of 3 : CH\_2015\_NA0035\_17\_41\_20150612\_00027.jpg



A view looking upstream from Woolner Ave. Summer 2014

Photo 3 of 3 : CH\_2015\_NA0035\_17\_41\_20150612\_00026.jpg



The inlet of the historical channel. Summer 2014

Rating **	A	Issue No.	<b>42</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.245298 °
Category	Rivers, Channels & Designated Flood			-122.068536 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_17_c_2012_42			

Action/Comments

Inspector Comments: No shoaling or sedimentation present.

No Photos

**\* Location**  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View				
Woolner Avenue / Up (cont)				
Rating **	A	Issue No.	43	GPS Lat/Long
Issue Type +	Ma	Location *		38.245298 °
Category	Rivers, Channels & Designated Flood			-122.068536 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_17_c _ 2012_43			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel.				

No Photos

No Photos

Rating **	A	Issue No.	44	GPS Lat/Long
Issue Type +	Ma	Location *		38.245298 °
Category	Rivers, Channels & Designated Flood			-122.068536 °
Item	Revetments			
DWR ID	DWR_NA0035_17_c _ 2012_44			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.				

No Photos

No Photos

Rating **	M	Issue No.	45	GPS Lat/Long
Issue Type +	Ma	Location *		38.245298 °
Category	Rivers, Channels & Designated Flood			-122.068536 °
Item	Encroachments			
DWR ID	DWR_NA0035_17_c _ 2012_45			
Action/Comments				
Inspector Comments: Suggest removal of cart from the channel.				

No Photos

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Woolner Avenue / Down**

Rating **	A	Issue No.	<b>46</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.245298 °
Category	Rivers, Channels & Designated Flood			-122.068536 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_17_c _ 2012_46			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Rating **	A	Issue No.	<b>46 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.245298 °
Category	Rivers, Channels & Designated Flood			-122.068536 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_17_c _ 2012_46			

Rating **	A	Issue No.	<b>46 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.245298 °
Category	Rivers, Channels & Designated Flood			-122.068536 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_17_c _ 2012_46			

Photo 1 of 3 : CH\_2015\_NA0035\_17\_46\_20150817\_00064.jpg




Looking downstream from Woolner Ave. Summer 2015.

Photo 2 of 3 : CH\_2015\_NA0035\_17\_46\_20150612\_00030.jpg



Looking downstream at the main channel from Woolner Ave. Summer 2014

Photo 3 of 3 : CH\_2015\_NA0035\_17\_46\_20150612\_00031.jpg



Looking at the downstream side of the historical channel from Woolner Ave. Summer 2014

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Woolner Avenue / Down (cont)**

Rating **	A	Issue No.	47	GPS Lat/Long
Issue Type +	Ma	Location *		38.245298 °
Category	Rivers, Channels & Designated Flood			-122.068536 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_17_c _ 2012_47			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	48	GPS Lat/Long
Issue Type +	Ma	Location *		38.245298 °
Category	Rivers, Channels & Designated Flood			-122.068536 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_17_c _ 2012_48			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel.				

No Photos

Rating **	A	Issue No.	49	GPS Lat/Long
Issue Type +	Ma	Location *		38.245298 °
Category	Rivers, Channels & Designated Flood			-122.068536 °
Item	Revetments			
DWR ID	DWR_NA0035_17_c _ 2012_49			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Woolner Avenue / Down (cont)**

Rating **	A	Issue No.	50	GPS Lat/Long
Issue Type +	Ma	Location *		38.245298 °
Category	Rivers, Channels & Designated Flood			-122.068536 °
Item	Encroachments			
DWR ID	DWR_NA0035_17_c _ 2012_50			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

Check Point / View

**Beck Avenue / Up**

Rating **	A	Issue No.	51	GPS Lat/Long
Issue Type +	Ma	Location *		38.243683 °
Category	Rivers, Channels & Designated Flood			-122.066470 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_17_c _ 2012_51			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Photo 1 of 3 : CH\_2015\_NA0035\_17\_51\_20150817\_00065.jpg



Looking upstream from Beck Ave. Summer 2015.

Photo 2 of 3 : CH\_2015\_NA0035\_17\_51\_20150612\_00035.jpg



A view of the upstream from Beck Ave. Summer 2014

Rating **	A	Issue No.	51 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		38.243683 °
Category	Rivers, Channels & Designated Flood			-122.066470 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_17_c _ 2012_51			

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Beck Avenue / Up (cont)**

Rating **	A	Issue No.	<b>51 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.243683 °
Category	Rivers, Channels & Designated Flood			-122.066470 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_17_c _ 2012_51			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Photo 3 of 3 : CH\_2015\_NA0035\_17\_51\_20150612\_00034.jpg



Upstream view of the historical channel from Beck Ave. Summer 2014

Rating **	A	Issue No.	<b>52</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.243683 °
Category	Rivers, Channels & Designated Flood			-122.066470 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_17_c _ 2012_52			

Action/Comments

Inspector Comments: No shoaling or sedimentation present.

No Photos

Rating **	A	Issue No.	<b>53</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.243683 °
Category	Rivers, Channels & Designated Flood			-122.066470 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_17_c _ 2012_53			

Action/Comments

Inspector Comments: No erosion or encroaching into the channel.

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Beck Avenue / Up (cont)**

Rating **	A	Issue No.	54	GPS Lat/Long
Issue Type +	Ma	Location *		38.243682 °
Category	Rivers, Channels & Designated Flood			-122.066469 °
Item	Revetments			
DWR ID	DWR_NA0035_17_c _ 2012_54			

Action/Comments

Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.

No Photos

Rating **	A	Issue No.	55	GPS Lat/Long
Issue Type +	Ma	Location *		38.243702 °
Category	Rivers, Channels & Designated Flood			-122.066538 °
Item	Encroachments			
DWR ID	DWR_NA0035_17_c _ 2012_55			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

Check Point / View

**Beck Avenue / Down**

Rating **	A	Issue No.	56	GPS Lat/Long
Issue Type +	Ma	Location *		38.243682 °
Category	Rivers, Channels & Designated Flood			-122.066469 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_17_c _ 2012_56			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Photo 1 of 3 : CH\_2015\_NA0035\_17\_56\_20150817\_00066.jpg



Looking downstream from Beck Ave. Summer 2015.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Beck Avenue / Down (cont)**

Rating **	A	Issue No.	<b>56 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.243682 °
Category	Rivers, Channels & Designated Flood			-122.066469 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_17_c _ 2012_56			

Action/Comments


Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Photo 2 of 3 : CH\_2015\_NA0035\_17\_56\_20150612\_00038.jpg



Downstream view of the main channel from Beck Ave. Summer 2014

Photo 3 of 3 : CH\_2015\_NA0035\_17\_56\_20150612\_00039.jpg



The historical channel from Beck Ave. looking downstream. Summer 2014

Rating **	A	Issue No.	<b>57</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.243682 °
Category	Rivers, Channels & Designated Flood			-122.066469 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_17_c _ 2012_57			

Action/Comments

Inspector Comments: No shoaling or sedimentation present.

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Beck Avenue / Down (cont)**

Rating **	A	Issue No.	<b>58</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.243682 °
Category	Rivers, Channels & Designated Flood			-122.066469 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_17_c _ 2012_58			

Action/Comments

Inspector Comments: No erosion encroaching into the channel.

No Photos

Rating **	A	Issue No.	<b>59</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.243682 °
Category	Rivers, Channels & Designated Flood			-122.066469 °
Item	Revetments			
DWR ID	DWR_NA0035_17_c _ 2012_59			

Action/Comments

Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.

No Photos

Rating **	A	Issue No.	<b>60</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.243702 °
Category	Rivers, Channels & Designated Flood			-122.066538 °
Item	Encroachments			
DWR ID	DWR_NA0035_17_c _ 2012_60			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

## Levee Inspection Report By Mile - Channel 2015

### Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

#### Highway 12 / Up

Rating **	M	Issue No.	<b>61</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.240567 °
Category	Rivers, Channels & Designated Flood			-122.062387 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_17_c_2012_61			

Action/Comments

Inspector Comments: Minimal scattered obstruction or vegetation. The flow is not impeded.

Rating **	M	Issue No.	<b>61 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.240567 °
Category	Rivers, Channels & Designated Flood			-122.062387 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_17_c_2012_61			

Rating **	M	Issue No.	<b>61 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.240567 °
Category	Rivers, Channels & Designated Flood			-122.062387 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_17_c_2012_61			

Photo 1 of 3 : CH\_2015\_NA0035\_17\_61\_20150817\_00067.jpg




Looking upstream from Highway 12. Summer 2015.

Photo 2 of 3 : CH\_2015\_NA0035\_17\_61\_20150612\_00043.jpg



Upstream view of the main channel from Highway 12. Summer 2014

Photo 3 of 3 : CH\_2015\_NA0035\_17\_61\_20150612\_00042.jpg



The outlet of the historical channel looking upstream from Highway 12. Summer 2014

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View				
Highway 12 / Up (cont)				
Rating **	A	Issue No.	62	GPS Lat/Long
Issue Type +	Ma	Location *		38.240567 °
Category	Rivers, Channels & Designated Flood			-122.062390 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_17_c _ 2012_62			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	63	GPS Lat/Long
Issue Type +	Ma	Location *		38.240567 °
Category	Rivers, Channels & Designated Flood			-122.062390 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_17_c _ 2012_63			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel.				

No Photos

Rating **	A	Issue No.	64	GPS Lat/Long
Issue Type +	Ma	Location *		38.240567 °
Category	Rivers, Channels & Designated Flood			-122.062390 °
Item	Revetments			
DWR ID	DWR_NA0035_17_c _ 2012_64			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.				
No Photos				

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Highway 12 / Up (cont)**

Rating **	A	Issue No.	<b>65</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.240590 °
Category	Rivers, Channels & Designated Flood			-122.062413 °
Item	Encroachments			
DWR ID	DWR_NA0035_17_c _ 2012_65			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

Check Point / View

**Highway 12 / Down**

Rating **	A	Issue No.	<b>66</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.240567 °
Category	Rivers, Channels & Designated Flood			-122.062390 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_17_c _ 2012_66			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Photo 1 of 2 : CH\_2015\_NA0035\_17\_66\_20150817\_00068.jpg



Looking downstream from Highway 12. Summer 2015.

Photo 2 of 2 : CH\_2015\_NA0035\_17\_66\_20150612\_00045.jpg



Looking downstream from Highway 12. Summer 2014

Rating **	A	Issue No.	<b>66 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.240567 °
Category	Rivers, Channels & Designated Flood			-122.062390 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_17_c _ 2012_66			

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Highway 12 / Down (cont)**

Rating **	A	Issue No.	67	GPS Lat/Long
Issue Type +	Ma	Location *		38.240567 °
Category	Rivers, Channels & Designated Flood			-122.062390 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_17_c _ 2012_67			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	68	GPS Lat/Long
Issue Type +	Ma	Location *		38.240567 °
Category	Rivers, Channels & Designated Flood			-122.062390 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_17_c _ 2012_68			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel.				

No Photos

Rating **	N	Issue No.	69	GPS Lat/Long
Issue Type +	Ma	Location *		38.240567 °
Category	Rivers, Channels & Designated Flood			-122.062390 °
Item	Revetments			
DWR ID	DWR_NA0035_17_c _ 2012_69			
Action/Comments				
Inspector Comments: This item does not apply to this inspection.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Highway 12 / Down (cont)**

Rating **	A	Issue No.	70	GPS Lat/Long
Issue Type +	Ma	Location *		38.240590 °
Category	Rivers, Channels & Designated Flood			-122.062413 °
Item	Encroachments			
DWR ID	DWR_NA0035_17_c _ 2012_70			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

Check Point / View

**Cordelia Road / Up**

Rating **	M	Issue No.	71	GPS Lat/Long
Issue Type +	Ma	Location *		38.233331 °
Category	Rivers, Channels & Designated Flood			-122.058608 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_17_c _ 2012_71			

Action/Comments

Inspector Comments: Vegetation growth of cattails or other obstruction impede the flow.

Photo 1 of 2 : CH\_2015\_NA0035\_17\_71\_20150817\_00069.jpg



Looking upstream from Cordelia Rd. Summer 2015.

Photo 2 of 2 : CH\_2015\_NA0035\_17\_71\_20150612\_00047.jpg



An upstream view of the channel from Cordelia Rd. Summer 2014

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Cordelia Road / Up (cont)**

Rating **	A	Issue No.	81	GPS Lat/Long
Issue Type +	Ma	Location *		38.233310 °
Category	Rivers, Channels & Designated Flood			-122.058590 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_17_c _ 2015_81			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	73	GPS Lat/Long
Issue Type +	Ma	Location *		38.233330 °
Category	Rivers, Channels & Designated Flood			-122.058608 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_17_c _ 2012_73			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel.				

No Photos

Rating **	N	Issue No.	74	GPS Lat/Long
Issue Type +	Ma	Location *		38.233330 °
Category	Rivers, Channels & Designated Flood			-122.058608 °
Item	Revetments			
DWR ID	DWR_NA0035_17_c _ 2012_74			
Action/Comments				
Inspector Comments: This item does not apply to this inspection.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Cordelia Road / Up (cont)**

Rating **	A	Issue No.	<b>75</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.233310 °
Category	Rivers, Channels & Designated Flood			-122.058590 °
Item	Encroachments			
DWR ID	DWR_NA0035_17_c _ 2012_75			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

Check Point / View

**Cordelia Road / Down**

Rating **	A	Issue No.	<b>76</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.233331 °
Category	Rivers, Channels & Designated Flood			-122.058607 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_17_c _ 2012_76			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Photo 1 of 2 : CH\_2015\_NA0035\_17\_76\_20150817\_00070.jpg



Looking downstream from Cordelia Rd. Summer 2015.

Photo 2 of 2 : CH\_2015\_NA0035\_17\_76\_20150612\_00051.jpg



A downstream view of the channel from Cordelia Rd. Summer 2014

Rating **	A	Issue No.	<b>76 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.233331 °
Category	Rivers, Channels & Designated Flood			-122.058607 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_17_c _ 2012_76			

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Cordelia Road / Down (cont)**

Rating **	A	Issue No.	77	GPS Lat/Long
Issue Type +	Ma	Location *		38.233332 °
Category	Rivers, Channels & Designated Flood			-122.058607 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_17_c _ 2012_77			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	78	GPS Lat/Long
Issue Type +	Ma	Location *		38.233332 °
Category	Rivers, Channels & Designated Flood			-122.058607 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_17_c _ 2012_78			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel.				

No Photos

Rating **	N	Issue No.	79	GPS Lat/Long
Issue Type +	Ma	Location *		38.233332 °
Category	Rivers, Channels & Designated Flood			-122.058607 °
Item	Revetments			
DWR ID	DWR_NA0035_17_c _ 2012_79			
Action/Comments				
Inspector Comments: The item does not apply to this inspection.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View				
Cordelia Road / Down (cont)				
Rating **	A	Issue No.	80	GPS Lat/Long
Issue Type +	Ma	Location *		38.233310 °
Category	Rivers, Channels & Designated Flood			-122.058590 °
Item	Encroachments			
DWR ID	DWR_NA0035_17_c _ 2012_80			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				
No Photos				

**\* Location**  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance****Unit Cover Sheet****2015 Channel Inspection Results****Fairfield Suisun Sewer District**

Channel
McCoy Creek

Channel Rating	<b>A</b>
Date of Inspection	08/05/2015 - 08/06/2015
DWR Inspector	Jai Lor
Accompanied By	Kevin Cullen City of Fairfield

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
McCoy Creek	1.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Bella Vista Dr / Up**

Rating **	A	Issue No.	1	GPS Lat/Long
Issue Type +	Ma	Location *		38.253280 °
Category	Rivers, Channels & Designated Flood			-122.000670 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_14_c _ 2012_1			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Photo 1 of 2 : CH\_2015\_NA0035\_14\_1\_20150817\_00023.jpg



View of the vegetation looking upstream of the channel. Summer 2015.

Photo 2 of 2 : CH\_2015\_NA0035\_14\_1\_20150612\_00002.jpg



Control structure is blocked by cattails. Remove or spray vegetation to open structure. Summer 2014

Rating **	A	Issue No.	2	GPS Lat/Long
Issue Type +	Ma	Location *		38.253219 °
Category	Rivers, Channels & Designated Flood			-122.000588 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_14_c _ 2012_2			

Action/Comments

Inspector Comments: No shoaling or sedimentation present.

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
McCoy Creek	1.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View				
Bella Vista Dr / Up (cont)				
Rating **	A	Issue No.	3	GPS Lat/Long
Issue Type +	Ma	Location *		38.253220 °
Category	Rivers, Channels & Designated Flood			-122.000588 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_14_c _ 2012_3			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel.				

No Photos

No Photos

Rating **	N	Issue No.	4	GPS Lat/Long
Issue Type +	Ma	Location *		38.253220 °
Category	Rivers, Channels & Designated Flood			-122.000587 °
Item	Revetments			
DWR ID	DWR_NA0035_14_c _ 2012_4			
Action/Comments				
Inspector Comments: This item does not apply to this inspection.				

No Photos

No Photos

Rating **	A	Issue No.	5	GPS Lat/Long
Issue Type +	Ma	Location *		38.253280 °
Category	Rivers, Channels & Designated Flood			-122.000670 °
Item	Encroachments			
DWR ID	DWR_NA0035_14_c _ 2012_5			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
McCoy Creek	1.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Bella Vista Dr / Down**

Rating **	M	Issue No.	<b>6</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.253280 °
Category	Rivers, Channels & Designated Flood			-122.000670 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_14_c _ 2012_6			

Action/Comments

Inspector Comments: Vegetation growth (such as cat tails, bull rushes, bushes or saplings) or other obstructions block approximately 25% of the capacity.

Photo 1 of 2 : CH\_2015\_NA0035\_14\_6\_20150817\_00025.jpg



View of the vegetation looking downstream. Summer 2015.

Photo 2 of 2 : CH\_2015\_NA0035\_14\_6\_20150612\_00007.jpg



Looking downstream at Bella Vista Ave. Woody vegetation is getting larger; need to remove. Summer 2014

Rating **	A	Issue No.	<b>7</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.253219 °
Category	Rivers, Channels & Designated Flood			-122.000588 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_14_c _ 2012_7			

Action/Comments

Inspector Comments: No shoaling or sedimentation present.

No Photos

**\* Location**  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
McCoy Creek	1.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Bella Vista Dr / Down (cont)**

Rating **	A	Issue No.	8	GPS Lat/Long
Issue Type +	Ma	Location *		38.253219 °
Category	Rivers, Channels & Designated Flood			-122.000588 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_14_c _ 2012_8			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel.				

No Photos

Rating **	N	Issue No.	9	GPS Lat/Long
Issue Type +	Ma	Location *		38.253220 °
Category	Rivers, Channels & Designated Flood			-122.000588 °
Item	Revetments			
DWR ID	DWR_NA0035_14_c _ 2012_9			
Action/Comments				
Inspector Comments: This item does not apply to this inspection.				

No Photos

Rating **	A	Issue No.	10	GPS Lat/Long
Issue Type +	Ma	Location *		38.253280 °
Category	Rivers, Channels & Designated Flood			-122.000670 °
Item	Encroachments			
DWR ID	DWR_NA0035_14_c _ 2012_10			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
McCoy Creek	1.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Emperor Dr / Up**

Rating **	M	Issue No.	11	GPS Lat/Long
Issue Type +	Ma	Location *		38.250738 °
Category	Rivers, Channels & Designated Flood			-122.004355 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_14_c _ 2012_11			

Action/Comments

Inspector Comments: Cat-tails need to be sprayed or removed at street crossing.

Photo 1 of 2 : CH\_2015\_NA0035\_14\_11\_20150817\_00026.jpg



View of the channel looking upstream. Summer 2015.

Rating **	M	Issue No.	11 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		38.250738 °
Category	Rivers, Channels & Designated Flood			-122.004355 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_14_c _ 2012_11			

Photo 2 of 2 : CH\_2015\_NA0035\_14\_11\_20150612\_00009.jpg



A view looking upstream from Emperor Dr. Summer 2014

Rating **	A	Issue No.	12	GPS Lat/Long
Issue Type +	Ma	Location *		38.250671 °
Category	Rivers, Channels & Designated Flood			-122.004419 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_14_c _ 2012_12			

Action/Comments

Inspector Comments: No shoaling or sedimentation present.

No Photos

**\* Location**  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
McCoy Creek	1.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View				
Emperor Dr / Up (cont)				
Rating **	A	Issue No.	13	GPS Lat/Long
Issue Type +	Ma	Location *		38.250671 °
Category	Rivers, Channels & Designated Flood			-122.004419 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_14_c _ 2012_13			
Action/Comments				
Inspector Comments: No erosion encroachment into the channel.				

No Photos

No Photos

Rating **	N	Issue No.	14	GPS Lat/Long
Issue Type +	Ma	Location *		38.250671 °
Category	Rivers, Channels & Designated Flood			-122.004419 °
Item	Revetments			
DWR ID	DWR_NA0035_14_c _ 2012_14			
Action/Comments				
Inspector Comments: This item does not apply to this inspection.				

No Photos

No Photos

Rating **	A	Issue No.	15	GPS Lat/Long
Issue Type +	Ma	Location *		38.250738 °
Category	Rivers, Channels & Designated Flood			-122.004355 °
Item	Encroachments			
DWR ID	DWR_NA0035_14_c _ 2012_15			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
McCoy Creek	1.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Emperor Dr / Down**

Rating **	M	Issue No.	16	GPS Lat/Long
Issue Type +	Ma	Location *		38.250671 °
Category	Rivers, Channels & Designated Flood			-122.004419 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_14_c _ 2012_16			
Action/Comments				
Inspector Comments: Cattails need to be sprayed or removed at street crossing. Try to maintain 50 ft. to 100 ft. clearance.				

Rating **	M	Issue No.	<b>16 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.250671 °
Category	Rivers, Channels & Designated Flood			-122.004419 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_14_c _ 2012_16			

Rating **	M	Issue No.	<b>16 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.250671 °
Category	Rivers, Channels & Designated Flood			-122.004419 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_14_c _ 2012_16			

Photo 1 of 3 : CH\_2015\_NA0035\_14\_16\_20150817\_00028.jpg



Woody vegetation looking downstream. Suggest removal of woody vegetation. Summer 2015.

Photo 2 of 3 : CH\_2015\_NA0035\_14\_16\_20150817\_00027.jpg



View of the vegetation looking downstream. Summer 2015.

Photo 3 of 3 : CH\_2015\_NA0035\_14\_16\_20150612\_00012.jpg



Looking downstream from Emperor Dr. Need to clear vegetation 50-100 feet from roadway. Summer 2014

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
McCoy Creek	1.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Emperor Dr / Down (cont)**

Rating **	A	Issue No.	17	GPS Lat/Long
Issue Type +	Ma	Location *		38.250671 °
Category	Rivers, Channels & Designated Flood			-122.004419 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_14_c _ 2012_17			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	18	GPS Lat/Long
Issue Type +	Ma	Location *		38.250671 °
Category	Rivers, Channels & Designated Flood			-122.004418 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_14_c _ 2012_18			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel.				

No Photos

Rating **	N	Issue No.	19	GPS Lat/Long
Issue Type +	Ma	Location *		38.250671 °
Category	Rivers, Channels & Designated Flood			-122.004418 °
Item	Revetments			
DWR ID	DWR_NA0035_14_c _ 2012_19			
Action/Comments				
Inspector Comments: This item does not apply to this inspection.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
McCoy Creek	1.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View				
Emperor Dr / Down (cont)				
Rating **	A	Issue No.	20	GPS Lat/Long
Issue Type +	Ma	Location *		38.250738 °
Category	Rivers, Channels & Designated Flood			-122.004355 °
Item	Encroachments			
DWR ID	DWR_NA0035_14_c _ 2012_20			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View				
Pintail Ave / Up				
Rating **	A	Issue No.	21	GPS Lat/Long
Issue Type +	Ma	Location *		38.248501
Category	Rivers, Channels & Designated Flood			-122.006344
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_14_c _ 2012_21			
Action/Comments				
Inspector Comments: Minimal scattered obstruction or vegetation. The flow is not impeded. Watch out for the vegetation growing.				

Photo 1 of 2 : CH\_2015\_NA0035\_14\_21\_20150817\_00029.jpg



View of the channel looking upstream. Summer 2015.

Photo 2 of 2 : CH\_2015\_NA0035\_14\_21\_20150612\_00014.jpg



A view looking upstream from Pintail Dr. Summer 2014

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
McCoy Creek	1.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Pintail Ave / Up (cont)**

Rating **	A	Issue No.	22	GPS Lat/Long
Issue Type +	Ma	Location *		38.248501 °
Category	Rivers, Channels & Designated Flood			-122.006345 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_14_c _ 2012_22			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	23	GPS Lat/Long
Issue Type +	Ma	Location *		38.248501 °
Category	Rivers, Channels & Designated Flood			-122.006346 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_14_c _ 2012_23			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel.				

No Photos

Rating **	A	Issue No.	24	GPS Lat/Long
Issue Type +	Ma	Location *		38.248501 °
Category	Rivers, Channels & Designated Flood			-122.006346 °
Item	Revetments			
DWR ID	DWR_NA0035_14_c _ 2012_24			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
McCoy Creek	1.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Pintail Ave / Up (cont)**

Rating **	A	Issue No.	<b>25</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.248542 °
Category	Rivers, Channels & Designated Flood			-122.006378 °
Item	Encroachments			
DWR ID	DWR_NA0035_14_c _ 2012_25			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

Check Point / View

**Pintail Ave / Down**

Rating **	M	Issue No.	<b>26</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.248501 °
Category	Rivers, Channels & Designated Flood			-122.006346 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_14_c _ 2012_26			

Action/Comments

Inspector Comments: Log jams, snags, vegetation growth (such as cat tails, bull rushes, bushes or saplings) or other obstructions block approximately 25% of the FCW.

Photo 1 of 3 : CH\_2015\_NA0035\_14\_26\_20150817\_00031.jpg



Suggest removal of tullies downstream. Summer 2015.

Photo 2 of 3 : CH\_2015\_NA0035\_14\_26\_20150817\_00030.jpg



View of the channel looking downstream. Summer 2015.

Rating **	M	Issue No.	<b>26 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.248501 °
Category	Rivers, Channels & Designated Flood			-122.006346 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_14_c _ 2012_26			

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
McCoy Creek	1.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Pintail Ave / Down (cont)**

Rating **	M	Issue No.	<b>26 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.248501 °
Category	Rivers, Channels & Designated Flood			-122.006346 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_14_c _ 2012_26			

Action/Comments

Inspector Comments: Log jams, snags, vegetation growth (such as cat tails, bull rushes, bushes or saplings) or other obstructions block approximately 25% of the FCW.

Photo 3 of 3 : CH\_2015\_NA0035\_14\_26\_20150612\_00017.jpg



A view looking downstream from Pintail Dr. Summer 2014

Rating **	A	Issue No.	<b>27</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.248501 °
Category	Rivers, Channels & Designated Flood			-122.006345 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_14_c _ 2012_27			

Action/Comments

Inspector Comments: No shoaling or sedimentation present.

No Photos

Rating **	A	Issue No.	<b>28</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.248500 °
Category	Rivers, Channels & Designated Flood			-122.006345 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_14_c _ 2012_28			

Action/Comments

Inspector Comments: No erosion encroaching into the channel.

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
McCoy Creek	1.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Pintail Ave / Down (cont)**

Rating **	A	Issue No.	29	GPS Lat/Long
Issue Type +	Ma	Location *		38.248500 °
Category	Rivers, Channels & Designated Flood			-122.006345 °
Item	Revetments			
DWR ID	DWR_NA0035_14_c _ 2012_29			

Action/Comments

Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.

No Photos

Rating **	A	Issue No.	30	GPS Lat/Long
Issue Type +	Ma	Location *		38.248542 °
Category	Rivers, Channels & Designated Flood			-122.006378 °
Item	Encroachments			
DWR ID	DWR_NA0035_14_c _ 2012_30			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

Check Point / View

**Anderson Dr / Up**

Rating **	M	Issue No.	31	GPS Lat/Long
Issue Type +	Ma	Location *		38.241537 °
Category	Rivers, Channels & Designated Flood			-122.012077 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_14_c _ 2012_31			

Action/Comments

Inspector Comments: Vegetation growth (such as cat tails, bull rushes, bushes or saplings) or other obstructions block approximately 25% of the FCW.

Photo 1 of 2 : CH\_2015\_NA0035\_14\_31\_20150817\_00032.jpg



View of the channel looking upstream. Summer 2015.

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
McCoy Creek	1.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Anderson Dr / Up (cont)**

Rating **	M	Issue No.	31 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		38.241537 °
Category	Rivers, Channels & Designated Flood			-122.012077 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_14_c _ 2012_31			
Action/Comments				
Inspector Comments: Vegetation growth (such as cat tails, bull rushes, bushes or saplings) or other obstructions block approximately 25% of the FCW.				

Photo 2 of 2 : CH\_2015\_NA0035\_14\_31\_20150612\_00019.jpg



Looking upstream from Anderson Dr. towards Highway 12. Summer 2014

Rating **	A	Issue No.	32	GPS Lat/Long
Issue Type +	Ma	Location *		38.241537 °
Category	Rivers, Channels & Designated Flood			-122.012077 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_14_c _ 2012_32			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	33	GPS Lat/Long
Issue Type +	Ma	Location *		38.241537 °
Category	Rivers, Channels & Designated Flood			-122.012077 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_14_c _ 2012_33			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
McCoy Creek	1.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Anderson Dr / Up (cont)**

Rating **	N	Issue No.	34	GPS Lat/Long
Issue Type +	Ma	Location *		38.241537 °
Category	Rivers, Channels & Designated Flood			-122.012077 °
Item	Revetments			
DWR ID	DWR_NA0035_14_c _ 2012_34			

Action/Comments

Inspector Comments: This item does not apply to this inspection.

No Photos

Rating **	A	Issue No.	35	GPS Lat/Long
Issue Type +	Ma	Location *		38.241537 °
Category	Rivers, Channels & Designated Flood			-122.012077 °
Item	Encroachments			
DWR ID	DWR_NA0035_14_c _ 2012_35			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present.

No Photos

Check Point / View

**Anderson Dr / Down**

Rating **	A	Issue No.	36	GPS Lat/Long
Issue Type +	Ma	Location *		38.241537 °
Category	Rivers, Channels & Designated Flood			-122.012077 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_14_c _ 2012_36			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Photo 1 of 2 : CH\_2015\_NA0035\_14\_36\_20150817\_00033.jpg



View of the channel looking downstream. Summer 2015.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
McCoy Creek	1.00	08/05/2015 08/06/2015	Jai Lor

Check Point / View

**Anderson Dr / Down (cont)**

Rating **	A	Issue No.	36 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		38.241537 °
Category	Rivers, Channels & Designated Flood			-122.012077 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_14_c_2012_36			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 2 of 2 : CH\_2015\_NA0035\_14\_36\_20150612\_00021.jpg



Looking downstream towards Suisun Bay from Anderson Dr. Summer 2014

Rating **	A	Issue No.	37	GPS Lat/Long
Issue Type +	Ma	Location *		38.241537 °
Category	Rivers, Channels & Designated Flood			-122.012077 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_14_c_2012_37			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	38	GPS Lat/Long
Issue Type +	Ma	Location *		38.241537 °
Category	Rivers, Channels & Designated Flood			-122.012077 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_14_c_2012_38			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
McCoy Creek	1.00	08/05/2015 08/06/2015	Jai Lor

Anderson Dr / Down (cont)

Rating **	N	Issue No.	39	GPS Lat/Long
Issue Type +	Ma	Location *		38.241537 °
Category	Rivers, Channels & Designated Flood			-122.012077 °
Item	Revetments			
DWR ID	DWR_NA0035_14_c _ 2012_39			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.				

No Photos

No Photos

No Photos

Rating **	A	Issue No.	40	GPS Lat/Long
Issue Type +	Ma	Location *		38.241537 °
Category	Rivers, Channels & Designated Flood			-122.012077 °
Item	Encroachments			
DWR ID	DWR_NA0035_14_c _ 2012_40			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance****Unit Cover Sheet****2015 Channel Inspection Results****Fairfield Suisun Sewer District**

Channel
Union Avenue Diversion

Channel Rating	<b>A</b>
Date of Inspection	08/06/2015
DWR Inspector	Jai Lor
Accompanied By	Kevin Cullen City of Fairfield

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Union Avenue Diversion	0.75	08/06/2015 08/06/2015	Jai Lor

Check Point / View

**N. Texas St / Down**

Rating **	A	Issue No.	<b>6</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.280585 °
Category	Rivers, Channels & Designated Flood			-122.034039 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_16_c _ 2012_6			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded. The palm trees should be removed.

Rating **	A	Issue No.	<b>6 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.280585 °
Category	Rivers, Channels & Designated Flood			-122.034039 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_16_c _ 2012_6			

Rating **	A	Issue No.	<b>6 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.280585 °
Category	Rivers, Channels & Designated Flood			-122.034039 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_16_c _ 2012_6			

Photo 1 of 3 : CH\_2015\_NA0035\_16\_6\_20150817\_00016.jpg



Looking downstream from N. Texas St. Summer 2015.

Photo 2 of 3 : CH\_2015\_NA0035\_16\_6\_20150612\_00003.jpg



Looking downstream from N. Texas St. Remove palm tree and heavy vegetation. Summer 2014

Photo 3 of 3 : CH\_2015\_NA0035\_16\_6\_20150612\_00002.jpg



Corrected issue at N. Texas St. 8-27-2014

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Union Avenue Diversion	0.75	08/06/2015 08/06/2015	Jai Lor

Check Point / View

**N. Texas St / Down (cont)**

Rating **	A	Issue No.	7	GPS Lat/Long
Issue Type +	Ma	Location *		38.280585 °
Category	Rivers, Channels & Designated Flood			-122.034039 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_16_c _ 2012_7			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	8	GPS Lat/Long
Issue Type +	Ma	Location *		38.280585 °
Category	Rivers, Channels & Designated Flood			-122.034039 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_16_c _ 2012_8			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel.				

No Photos

Rating **	A	Issue No.	9	GPS Lat/Long
Issue Type +	Ma	Location *		38.280585 °
Category	Rivers, Channels & Designated Flood			-122.034039 °
Item	Revetments			
DWR ID	DWR_NA0035_16_c _ 2012_9			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Union Avenue Diversion	0.75	08/06/2015 08/06/2015	Jai Lor

Check Point / View				
N. Texas St / Down (cont)				
Rating **	A	Issue No.	10	GPS Lat/Long
Issue Type +	Ma	Location *		38.280585 °
Category	Rivers, Channels & Designated Flood			-122.034039 °
Item	Encroachments			
DWR ID	DWR_NA0035_16_c _ 2012_10			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View				
Camrose Ave / Up				
Rating **	A	Issue No.	11	GPS Lat/Long
Issue Type +	Ma	Location *		38.281544
Category	Rivers, Channels & Designated Flood			-122.030546
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_16_c _ 2012_11			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 3 : CH\_2015\_NA0035\_16\_11\_20150817\_00017.jpg



Looking upstream from Camrose Ave. Summer 2015.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Union Avenue Diversion	0.75	08/06/2015 08/06/2015	Jai Lor

Check Point / View

**Camrose Ave / Up (cont)**

Rating **	A	Issue No.	<b>11 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.281544 °
Category	Rivers, Channels & Designated Flood			-122.030546 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_16_c _ 2012_11			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Photo 2 of 3 : CH\_2015\_NA0035\_16\_11\_20150817\_00018.jpg



Suggest removal of palm tree before it grows looking upstream from Camrose Ave. Summer 2015.

Rating **	A	Issue No.	<b>11 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.281544 °
Category	Rivers, Channels & Designated Flood			-122.030546 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_16_c _ 2012_11			

Photo 3 of 3 : CH\_2015\_NA0035\_16\_11\_20150612\_00004.jpg



Looking upstream from Camrose Ave. Summer 2014

Rating **	A	Issue No.	<b>12</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.281544 °
Category	Rivers, Channels & Designated Flood			-122.030545 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_16_c _ 2012_12			

Action/Comments

Inspector Comments: No shoaling or sedimentation present.

No Photos

**\* Location**  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Union Avenue Diversion	0.75	08/06/2015 08/06/2015	Jai Lor

Check Point / View				
Camrose Ave / Up (cont)				
Rating **	A	Issue No.	13	GPS Lat/Long
Issue Type +	Ma	Location *		38.281544 °
Category	Rivers, Channels & Designated Flood			-122.030546 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_16_c _ 2012_13			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel.				

No Photos

No Photos

Rating **	A	Issue No.	14	GPS Lat/Long
Issue Type +	Ma	Location *		38.281668 °
Category	Rivers, Channels & Designated Flood			-122.030495 °
Item	Revetments			
DWR ID	DWR_NA0035_16_c _ 2012_14			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.				

No Photos

No Photos

Rating **	A	Issue No.	15	GPS Lat/Long
Issue Type +	Ma	Location *		38.281668 °
Category	Rivers, Channels & Designated Flood			-122.030495 °
Item	Encroachments			
DWR ID	DWR_NA0035_16_c _ 2012_15			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Union Avenue Diversion	0.75	08/06/2015 08/06/2015	Jai Lor

Check Point / View

**Camrose Ave / Down**

Rating **	A	Issue No.	<b>16</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.281544 °
Category	Rivers, Channels & Designated Flood			-122.030543 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_16_c_2012_16			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Photo 1 of 2 : CH\_2015\_NA0035\_16\_16\_20150817\_00019.jpg



Looking downstream from Camrose Ave. Summer 2015.

Rating **	A	Issue No.	<b>16 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.281544 °
Category	Rivers, Channels & Designated Flood			-122.030543 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_16_c_2012_16			

Photo 2 of 2 : CH\_2015\_NA0035\_16\_16\_20150612\_00006.jpg



A view downstream from Camrose Ave. Summer 2014

Rating **	A	Issue No.	<b>17</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.281545 °
Category	Rivers, Channels & Designated Flood			-122.030543 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_16_c_2012_17			

Action/Comments

Inspector Comments: No shoaling or sedimentation present.

No Photos

**\* Location**  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Union Avenue Diversion	0.75	08/06/2015 08/06/2015	Jai Lor

Check Point / View				
Camrose Ave / Down (cont)				
Rating **	A	Issue No.	18	GPS Lat/Long
Issue Type +	Ma	Location *		38.281545
Category	Rivers, Channels & Designated Flood			-122.030544
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_16_c _ 2012_18			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel.				

No Photos

Rating **	A	Issue No.	19	GPS Lat/Long
Issue Type +	Ma	Location *		38.281546
Category	Rivers, Channels & Designated Flood			-122.030544
Item	Revetments			
DWR ID	DWR_NA0035_16_c _ 2012_19			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.				

Photo 1 of 1 : CH\_2015\_NA0035\_16\_19\_20150817\_00020.jpg



View of the revetment on the right bank looking downstream. Summer 2015.

Rating **	A	Issue No.	20	GPS Lat/Long
Issue Type +	Ma	Location *		38.281668
Category	Rivers, Channels & Designated Flood			-122.030495
Item	Encroachments			
DWR ID	DWR_NA0035_16_c _ 2012_20			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Union Avenue Diversion	0.75	08/06/2015 08/06/2015	Jai Lor

Check Point / View

**Dover Ave / Up**

Rating **	A	Issue No.	<b>21</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.280944 °
Category	Rivers, Channels & Designated Flood			-122.025035 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_16_c _ 2012_21			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Photo 1 of 2 : CH\_2015\_NA0035\_16\_21\_20150817\_00021.jpg



Looking upstream from Dover Ave. Summer 2015.

Rating **	A	Issue No.	<b>21 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.280944 °
Category	Rivers, Channels & Designated Flood			-122.025035 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_16_c _ 2012_21			

Photo 2 of 2 : CH\_2015\_NA0035\_16\_21\_20150612\_00008.jpg



A view looking upstream from Dover Ave. Summer 2014

Rating **	A	Issue No.	<b>22</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.280946 °
Category	Rivers, Channels & Designated Flood			-122.025034 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_16_c _ 2012_22			

Action/Comments

Inspector Comments: No shoaling or sedimentation present.

No Photos

**\* Location**  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Union Avenue Diversion	0.75	08/06/2015 08/06/2015	Jai Lor

Check Point / View				
Dover Ave / Up (cont)				
Rating **	A	Issue No.	23	GPS Lat/Long
Issue Type +	Ma	Location *		38.280945 °
Category	Rivers, Channels & Designated Flood			-122.025035 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_16_c _ 2012_23			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel.				

No Photos

No Photos

Rating **	A	Issue No.	24	GPS Lat/Long
Issue Type +	Ma	Location *		38.280946 °
Category	Rivers, Channels & Designated Flood			-122.025034 °
Item	Revetments			
DWR ID	DWR_NA0035_16_c _ 2012_24			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.				

No Photos

No Photos

Rating **	A	Issue No.	25	GPS Lat/Long
Issue Type +	Ma	Location *		38.280990 °
Category	Rivers, Channels & Designated Flood			-122.024750 °
Item	Encroachments			
DWR ID	DWR_NA0035_16_c _ 2012_25			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Union Avenue Diversion	0.75	08/06/2015 08/06/2015	Jai Lor

Check Point / View

**Dover Ave / Down**

Rating **	A	Issue No.	26	GPS Lat/Long
Issue Type +	Ma	Location *		38.280946 °
Category	Rivers, Channels & Designated Flood			-122.025034 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_16_c _ 2012_26			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 2 : CH\_2015\_NA0035\_16\_26\_20150817\_00022.jpg



Looking downstream from Dover Ave. Woody vegetation has been removed. Summer 2015.

Rating **	A	Issue No.	<b>26 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.280946 °
Category	Rivers, Channels & Designated Flood			-122.025034 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_16_c _ 2012_26			

Photo 2 of 2 : CH\_2015\_NA0035\_16\_26\_20150612\_00010.jpg



Looking downstream from Dover Ave. Summer 2014. Remove small woody vegetation.

Rating **	A	Issue No.	27	GPS Lat/Long
Issue Type +	Ma	Location *		38.280947 °
Category	Rivers, Channels & Designated Flood			-122.025034 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_16_c _ 2012_27			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Union Avenue Diversion	0.75	08/06/2015 08/06/2015	Jai Lor

Check Point / View				
Dover Ave / Down (cont)				
Rating **	A	Issue No.	28	GPS Lat/Long
Issue Type +	Ma	Location *		38.280947 °
Category	Rivers, Channels & Designated Flood			-122.025035 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_16_c _ 2012_28			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel.				

No Photos

No Photos

Rating **	A	Issue No.	29	GPS Lat/Long
Issue Type +	Ma	Location *		38.280947 °
Category	Rivers, Channels & Designated Flood			-122.025033 °
Item	Revetments			
DWR ID	DWR_NA0035_16_c _ 2012_29			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.				

No Photos

No Photos

Rating **	A	Issue No.	30	GPS Lat/Long
Issue Type +	Ma	Location *		38.280990 °
Category	Rivers, Channels & Designated Flood			-122.024750 °
Item	Encroachments			
DWR ID	DWR_NA0035_16_c _ 2012_30			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Union Avenue Diversion	0.75	08/06/2015 08/06/2015	Jai Lor

Check Point / View

**Gulf Dr / Up**

Rating **	A	Issue No.	<b>31</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.280937 °
Category	Rivers, Channels & Designated Flood			-122.020628 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_16_c_2012_31			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Photo 1 of 2 : CH\_2015\_NA0035\_16\_31\_20150817\_00023.jpg



Looking upstream from Gulf Dr. Summer 2015.

Rating **	A	Issue No.	<b>31 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.280937 °
Category	Rivers, Channels & Designated Flood			-122.020628 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_16_c_2012_31			

Photo 2 of 2 : CH\_2015\_NA0035\_16\_31\_20150612\_00012.jpg



A view looking upstream from Gulf Dr. Summer 2014

Rating **	A	Issue No.	<b>32</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.280937 °
Category	Rivers, Channels & Designated Flood			-122.020628 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_16_c_2012_32			

Action/Comments

Inspector Comments: No shoaling or sedimentation present.

No Photos

**\* Location**  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Union Avenue Diversion	0.75	08/06/2015 08/06/2015	Jai Lor

Check Point / View				
Gulf Dr / Up (cont)				
Rating **	A	Issue No.	33	GPS Lat/Long
Issue Type +	Ma	Location *		38.280937 °
Category	Rivers, Channels & Designated Flood			-122.020628 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_16_c _ 2012_33			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel.				

No Photos

No Photos

Rating **	A	Issue No.	34	GPS Lat/Long
Issue Type +	Ma	Location *		38.280937 °
Category	Rivers, Channels & Designated Flood			-122.020628 °
Item	Revetments			
DWR ID	DWR_NA0035_16_c _ 2012_34			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.				

No Photos

No Photos

Rating **	A	Issue No.	35	GPS Lat/Long
Issue Type +	Ma	Location *		38.281002 °
Category	Rivers, Channels & Designated Flood			-122.020570 °
Item	Encroachments			
DWR ID	DWR_NA0035_16_c _ 2012_35			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Union Avenue Diversion	0.75	08/06/2015 08/06/2015	Jai Lor

Check Point / View

**Gulf Dr / Down**

Rating **	A	Issue No.	36	GPS Lat/Long
Issue Type +	Ma	Location *		38.280937 °
Category	Rivers, Channels & Designated Flood			-122.020629 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_16_c_2012_36			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 2 : CH\_2015\_NA0035\_16\_36\_20150817\_00024.jpg



Looking downstream from Gulf Dr. Summer 2015.

Rating **	A	Issue No.	<b>36 (cont)</b>	GPS Lat/Long
Issue Type +	Ma	Location *		38.280937 °
Category	Rivers, Channels & Designated Flood			-122.020629 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0035_16_c_2012_36			

Photo 2 of 2 : CH\_2015\_NA0035\_16\_36\_20150612\_00014.jpg



A view looking downstream from Gulf Dr. Summer 2014

Rating **	A	Issue No.	37	GPS Lat/Long
Issue Type +	Ma	Location *		38.280938 °
Category	Rivers, Channels & Designated Flood			-122.020629 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0035_16_c_2012_37			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

**\* Location**  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Channel 2015**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Union Avenue Diversion	0.75	08/06/2015 08/06/2015	Jai Lor

Check Point / View				
Gulf Dr / Down (cont)				
Rating **	A	Issue No.	38	GPS Lat/Long
Issue Type +	Ma	Location *		38.280938 °
Category	Rivers, Channels & Designated Flood			-122.020629 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0035_16_c _ 2012_38			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel.				

No Photos

No Photos

Rating **	A	Issue No.	39	GPS Lat/Long
Issue Type +	Ma	Location *		38.280938 °
Category	Rivers, Channels & Designated Flood			-122.020629 °
Item	Revetments			
DWR ID	DWR_NA0035_16_c _ 2012_39			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.				

No Photos

No Photos

Rating **	A	Issue No.	40	GPS Lat/Long
Issue Type +	Ma	Location *		38.281002 °
Category	Rivers, Channels & Designated Flood			-122.020570 °
Item	Encroachments			
DWR ID	DWR_NA0035_16_c _ 2012_40			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

No Photos

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---